

WA 2917 4e

9/30/1988

CHEMICAL PROCESSORS INC. PIER #91
DAILY PLANT INSPECTION REPORT

The following tanks were inspected for corrosion , leaking valves , seams and manholes.

TANK #	O.K.	NEEDS REPAIR	TANK #	O.K.	NEEDS REPAIR
90	✓		108	✓	
94	✓		109	✓	
96	✓		110	✓	
97	✓		111	✓	
98	✓		112	✓	
99	✓		113	✓	
100	✓		114	✓	
105	✓		115	✓	
106	✓		116	✓	
107	✓		117	✓	
C.T.	✓		118	✓	
165	✓				

FILE COPY

SMALL YARD BERMS O.K. ✓ NEEDS REPAIR

M.D.O. YARD BERMS O.K. ✓ NEEDS REPAIR

B.O. YARDS BERMS O.K. ✓ NEEDS REPAIR

BLDG. #21 O.K. ✓ NEEDS REPAIR

FOAM PUMPS O.K. ✓ NEEDS REPAIR

TESTED

9/26/88

COMMENTS :

DRUM STORAGE AREA

ok

USEPA RCRA



3012746

TIME OF INSPECTION

0730

INSPECTED BY PRINT: Nate Mathews SIGN: Nate Mathews DATE: 9-30-88

CHEMICAL PROCESSORS INC PIER #91
DAILY PLANT INSPECTION REPORT

The following tanks were inspected for corrosion , leaking valves , seams and manholes.

TANK #	O.K.	NEEDS REPAIR	TANK #	O.K.	NEEDS REPAIR
90	✓		108	✓	
94	✓		109	✓	
95	✓		110	✓	
97	✓		111	✓	
98	✓		112	✓	
99	✓		113	✓	
100	✓		114	✓	
105	✓		115	✓	
106	✓		116	✓	
107	✓		117	✓	
G.T.	✓		118	✓	
165	✓				

SMALL YARD BERMS O.K. ✓ NEEDS REPAIR

M.D.O. YARD BERMS O.K. ✓ NEEDS REPAIR

B.O. YARDS BERMS O.K. ✓ NEEDS REPAIR

BLDG. #21 O.K. ✓ NEEDS REPAIR

FOAM PUMPS O.K. ✓ NEEDS REPAIR

TESTED 9-26-88

COMMENTS :

DRUM STORAGE AREA

OK

TIME OF INSPECTION 0730

INSPECTED BY PRINT: *Nate Mathews* SIGN: *Nate Mathews* DATE: 9-29-88

CHEMICAL PROCESSORS INC. PIER #91
DAILY PLANT INSPECTION REPORT

The following tanks were inspected for corrosion , leaking valves , seams and manholes.

TANK #	O.K.	NEEDS REPAIR	TANK #	O.K.	NEEDS REPAIR
90	✓		108	✓	
94	✓		109	✓	
95	✓		110	✓	
97	✓		111	✓	
98	✓		112	✓	
99	✓		113	✓	
100	✓		114	✓	
105	✓		115	✓	
106	✓		116	✓	
107	✓		117	✓	
C.T.	✓		118	✓	
165	✓				

SMALL YARD BERMS O.K. ✓ NEEDS REPAIR

M.D.O. YARD BERMS O.K. ✓ NEEDS REPAIR

B.O. YARDS BERMS O.K. ✓ NEEDS REPAIR

BLDG. #21 O.K. ✓ NEEDS REPAIR

FOAM PUMPS O.K. ✓ NEEDS REPAIR

TESTED 9-26-88

COMMENTS :

DRUM STORAGE AREA OK

TIME OF INSPECTION 0730

INSPECTED BY PRINT: Nate Mathews SIGN: Nate Mathews DATE: 9-28-88

CHEMICAL PROCESSORS INC. PIER #91
DAILY PLANT INSPECTION REPORT

The following tanks were inspected for corrosion, leaking valves, seams and manholes.

TANK #	O.K.	NEEDS REPAIR	TANK #	O.K.	NEEDS REPAIR
90	/		108	/	
94	/		109	/	
96	/		110	/	
97	/		111	/	
98	/		112	/	
99	/		113	/	
100	/		114	/	
105	/		115	/	
106	/		116	/	
107	/		117	/	
C.T.	/		118	/	
165	/				

SMALL YARD BERMS O.K. / NEEDS REPAIR

M.D.O. YARD BERMS O.K. / NEEDS REPAIR

B.O. YARDS BERMS O.K. / NEEDS REPAIR

BLDG. #21 O.K. / NEEDS REPAIR

FOAM PUMPS O.K. / NEEDS REPAIR

TESTED 9-26-88

COMMENTS :

DRUM STORAGE AREA OK

TIME OF INSPECTION 0730

INSPECTED BY PRINT: Nate Mathews SIGN: Nate Mathews DATE: 9-27-88

CHEMICAL PROCESSORS INC. PIER #91
DAILY PLANT INSPECTION REPORT

The following tanks were inspected for corrosion , leaking valves , seams and manholes.

TANK #	O.K.	NEEDS REPAIR	TANK #	O.K.	NEEDS REPAIR
90	/		108	/	
94	/		109	/	
96	/		110	/	
97	/		111	/	
98	/		112	/	
99	/		113	/	
100	/		114	/	
105	/		115	/	
106	/		116	/	
107	/		117	/	
C.T.	/		118	/	
165	/				

SMALL YARD BERMS O.K. / NEEDS REPAIR

M.D.O. YARD BERMS O.K. / NEEDS REPAIR

B.O. YARDS BERMS O.K. / NEEDS REPAIR

BLDG. #21 O.K. / NEEDS REPAIR

FOAM PUMPS O.K. / NEEDS REPAIR

TESTED 9-26-86

COMMENTS :

DRUM STORAGE AREA CK

TIME OF INSPECTION 0930

INSPECTED BY PRINT: Patricia M. Morris SIGN: Patricia M. Morris DATE: 9-26-86